

☐

Run Train # 610

Westbound

to

LouisAnthony

City/Town: LouisAnthony

Division: Blue

	AAR	Road	#	Waybill #	Rolling Stock ID	Action	Industry Stop	Industry Siding	Arrive/Depart
1	XM	TPFX	5515	109	TPFX5515	Pickup	LouisAnthonyYd	LAY003	20:30 - 20:35
2	XM	PRR	19374	119	PRR19374	Pickup	LouisAnthonyYd	LAY003	20:30 - 20:35
3	HFA	FEC	15542	169	FEC15542	Pickup	LouisAnthonyYd	LAY003	20:30 - 20:35

☐

Run Train # 610

Westbound

to

SouthAnthonyville

City/Town: SouthAnthonyville

Division: Blue

	AAR	Road	#	Waybill #	Rolling Stock ID	Action	Industry Stop	Industry Siding	Arrive/Depart
4	HFA	CO	82525	158	CO82525	Pickup	TristarFeMineShip	SAV030	20:35 - 20:40
5	HFA	FEC	15542	169	FEC15542	Setout	TristarFeMineShip	SAV030	20:35 - 20:40

☐

Run Train # 610

Westbound

to

MTS Industrial Park

City/Town: MTS Industrial Park

Division: Blue

	AAR	Road	#	Waybill #	Rolling Stock ID	Action	Industry Stop	Industry Siding	Arrive/Depart
6	HFA	BO	189090	78	B&O189090-2	Pickup	HollandIronRcve	MIP020	20:40 - 20:45
7	XM	CO	495671	152	C&O495671	Pickup	MaytagFactoryShip	MIP030	20:45 - 20:50
9	XM	TPFX	5515	109	TPFX5515	Setout	MaytagFactoryRcve	MIP030	20:55 - 21:00

Switchlist

Notes:

☐

Run Train # 610

Westbound

to

Durose International

City/Town: Durose International

Division: Blue

	AAR	Road	#	Waybill #	Rolling Stock ID	Action	Industry Stop	Industry Siding	Arrive/Depart
10	XM	ROCK	48750	164	ROCK48750	Pickup	DIA	DIACargo010	21:00 - 21:05
11	XM	PRR	19374	119	PRR19374	Setout	DIA Customs	DIACargo020	21:05 - 21:10

☐

Run Train # 610

Westbound

to

LouisAnthony

City/Town: LouisAnthony

Division: Blue

	AAR	Road	#	Waybill #	Rolling Stock ID	Action	Industry Stop	Industry Siding	Arrive/Depart
12	HFA	BO	189090	78	B&O189090-2	Setout	LouisAnthonyYd	LAY003	21:10 - 21:15
13	XM	CO	495671	152	C&O495671	Setout	LouisAnthonyYd	LAY003	21:10 - 21:15
14	HFA	CO	82525	158	CO82525	Setout	LouisAnthonyYd	LAY003	21:10 - 21:15
15	XM	ROCK	48750	164	ROCK48750	Setout	LouisAnthonyYd	LAY003	21:10 - 21:15